

**Flood Control Project Maintenance
Levee Inspections**

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including Boat Survey Erosion

Sacramento River Basin

RD0900	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 0900	U	13.60				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Vegetation	4.09	0.64	6.65	48.90%		
Trim / Thin Trees	1.27	0.12	1.75	12.87%		
Encroachments	0.02		0.02	0.15%	0.16	
Animal Control	0.29		0.29	2.13%		
Cracking	0.02		0.02	0.15%		
Crown Surface / Depressions / Rutting	1.64	0.18	2.36	17.35%		
Boat Survey Erosion		0.01	0.04	0.29%		
<i>LMA Totals:</i>	7.33	0.95	11.13	81.84%	0.16	0.00

Unit No. 01 Sacramento River	Overall Unit Rating	Total Unit Miles				
	U	7.90				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Vegetation	4.07	0.43	5.79	73.29%		
Trim / Thin Trees	1.27	0.12	1.75	22.15%		
Encroachments	0.02		0.02	0.25%	0.16	
Animal Control	0.01		0.01	0.13%		
Crown Surface / Depressions / Rutting	1.64		1.64	20.76%		
Boat Survey Erosion		0.01	0.04	0.51%		
<i>Unit Totals:</i>	7.01	0.56	9.25	117.09%	0.16	0.00

Unit No. 02 Yolo Bypass	Overall Unit Rating	Total Unit Miles				
	U	5.70				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Vegetation	0.02	0.21	0.86	15.09%		
Animal Control	0.28		0.28	4.91%		
Cracking	0.02		0.02	0.35%		
Crown Surface / Depressions / Rutting		0.18	0.72	12.63%		
<i>Unit Totals:</i>	0.32	0.39	1.88	32.98%	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Fall 2008 Levee Inspection Results

Reclamation District No. 0900

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)			U	

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

*

SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2008 Levee Inspection Results

Reclamation District No. 0900

Waterway			Bank	Unit Miles
Unit No. 01 Sacramento River			Right	7.90
	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	3/26/2008		9/24/2008	
DWR Inspector	Richard Willoughby		David Pesavento	
Accompanied By				
Unit Maintenance Rating (Fall Only)			U	

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

Reclamation District No. 0900

Waterway						Bank	Unit Miles	Inspection Date		Inspector	
Unit No. 01 Sacramento River						Right	7.90	09/24/2008		David Pesavento	
LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	1.93	2.27	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.559673 ° -121.518404 °	38.555341 ° -121.516193 °	Y	46
2	2.04	2.06	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.558527 ° -121.517495 °	38.558200 ° -121.517392 °		3
3	2.11	2.13	Earthen Levee	Vegetation	LS	U	Elderberries are blocking visibility and flood fight capability.	38.557502 ° -121.517167 °	38.557228 ° -121.517047 °		5
4	2.20	2.27	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.556342 ° -121.516680 °	38.555280 ° -121.516197 °		6
5	2.21	2.24	Earthen Levee	Vegetation	LS	U	Elderberries are blocking visibility and flood fight capability.	38.556178 ° -121.516613 °	38.555802 ° -121.516425 °		7
6	2.24	2.27	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.555802 ° -121.516388 °	38.555341 ° -121.516195 °		47
7	2.32	2.53	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.554723 ° -121.515926 °	38.551771 ° -121.515023 °		48
8	2.36	2.40	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.554125 ° -121.515687 °	38.553523 ° -121.515487 °		8
9	2.45	2.45	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.552853 ° -121.515270 °	38.552853 ° -121.515270 °		9
10	2.52	2.52	Earthen Levee	Animal Control	WS	M	Exterminate rodents and backfill and compact or grout burrows.	38.551875 ° -121.515050 °	38.551875 ° -121.515050 °		49
11	2.53	2.57	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.551695 ° -121.514982 °	38.551210 ° -121.514863 °		10
12	2.56	2.64	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.551278 ° -121.514877 °	38.550235 ° -121.514577 °	Y	11
13	2.62	2.62	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.550428 ° -121.514640 °	38.550428 ° -121.514640 °		12
14	2.86	2.90	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.547241 ° -121.513142 °	38.546630 ° -121.512827 °		50
15	3.11	3.28	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.543660 ° -121.512639 °	38.541497 ° -121.513778 °		51
16	3.33	3.47	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.540871 ° -121.514229 °	38.539326 ° -121.515894 °		52
17	3.43	3.69	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.539683 ° -121.515407 °	38.537303 ° -121.519118 °		14
18	3.51	3.62	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.538927 ° -121.516496 °	38.537961 ° -121.518004 °		53
19	3.70	3.70	Boat Survey	Boat Survey Erosion	LS	U	Inspector Comments: tree hazards, caves, tension cracks, slumping	° °	° °		951

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

Reclamation District No. 0900

Waterway						Bank	Unit Miles	Inspection Date		Inspector	
Unit No. 01 Sacramento River						Right	7.90	09/24/2008		David Pesavento	
LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
20	3.71	3.75	Earthen Levee	Encroachments	WS PO		Landscaping	38.537213 ° -121.519363 °	38.536833 ° -121.520087 °		15
21	3.72	4.14	Earthen Levee	Vegetation	LS M		Remove the wild growth other than native grasses from the levee slopes.	38.537106 ° -121.519502 °	38.534196 ° -121.526400 °		54
22	3.83	4.04	Earthen Levee	Trim / Thin Trees	WS M		Trim trees to at least five feet above ground level.	38.536205 ° -121.521358 °	38.534902 ° -121.524687 °		16
23	4.07	4.08	Earthen Levee	Trim / Thin Trees	WS M		Trim trees to at least five feet above ground level.	38.534678 ° -121.525180 °	38.534580 ° -121.525438 °		17
24	4.15	4.24	Earthen Levee	Trim / Thin Trees	LS M		Trim trees to at least five feet above ground level.	38.534167 ° -121.526470 °	38.533582 ° -121.527960 °		19
25	4.25	4.25	Earthen Levee	Vegetation	WS U		Remove the wild growth other than native grasses from the levee slopes.	38.533414 ° -121.528158 °	38.533414 ° -121.528158 °	Y	77
26	4.26	4.53	Earthen Levee	Vegetation	LS M		Remove the wild growth other than native grasses from the levee slopes.	38.533447 ° -121.528301 °	38.530722 ° -121.531810 °	Y	55
27	4.61	4.84	Earthen Levee	Vegetation	LS M		Remove the wild growth other than native grasses from the levee slopes.	38.529614 ° -121.532102 °	38.526367 ° -121.531039 °		56
28	4.77	4.87	Earthen Levee	Trim / Thin Trees	WS M		Trim trees to at least five feet above ground level.	38.527302 ° -121.531642 °	38.526083 ° -121.530728 °		20
29	4.99	5.04	Earthen Levee	Vegetation	LS M		Remove the wild growth other than native grasses from the levee slopes.	38.524637 ° -121.529422 °	38.524119 ° -121.528846 °		57
30	5.05	5.05	Earthen Levee	Trim / Thin Trees	WS M		Trim trees to at least five feet above ground level.	38.524037 ° -121.528685 °	38.524037 ° -121.528685 °		21
31	5.39	5.69	Earthen Levee	Vegetation	LS M		Remove the wild growth other than native grasses from the levee slopes.	38.520189 ° -121.525718 °	38.518259 ° -121.530502 °		58
32	5.53	5.53	Earthen Levee	Trim / Thin Trees	LS M		Trim trees to at least five feet above ground level.	38.518973 ° -121.527718 °	38.518973 ° -121.527718 °		22
33	5.58	5.63	Earthen Levee	Encroachments	LS PO		Landscaping	38.518710 ° -121.528513 °	38.518492 ° -121.529410 °		23
34	5.81	5.83	Earthen Levee	Trim / Thin Trees	LS M		Thin trees to allow visibility of the ground and room to flood fight.	38.518037 ° -121.532817 °	38.518004 ° -121.533132 °		59
35	5.85	5.95	Earthen Levee	Vegetation	WS M		Remove the wild growth other than native grasses from the levee slopes.	38.517934 ° -121.535256 °	38.517934 ° -121.535256 °		76
36	5.86	6.05	Earthen Levee	Vegetation	LS M		Remove the wild growth other than native grasses from the levee slopes.	38.517995 ° -121.533652 °	38.517922 ° -121.537234 °		60
37	5.87	5.89	Earthen Levee	Vegetation	LS U		Remove the wild growth other than native grasses from the levee slopes.	38.517990 ° -121.533843 °	38.517988 ° -121.534212 °		24
38	5.97	5.98	Earthen Levee	Vegetation	LS U		Elderberries are blocking visibility and flood fight capability.	38.517952 ° -121.535672 °	38.517948 ° -121.535857 °		25

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

Reclamation District No. 0900

Waterway						Bank	Unit Miles	Inspection Date		Inspector	
Unit No. 01 Sacramento River						Right	7.90	09/24/2008		David Pesavento	
LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
39	6.04	6.06	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.517927 ° -121.537058 °	38.517917 ° -121.537430 °		26
40	6.13	6.21	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.517908 ° -121.538566 °	38.517760 ° -121.540127 °		61
41	6.25	6.28	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.517677 ° -121.540923 °	38.517610 ° -121.541398 °	Y	27
42	6.27	6.27	Earthen Levee	Encroachments	LS	M	Prunings	38.517613 ° -121.541249 °	38.517613 ° -121.541249 °	Y	62
43	6.37	6.44	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.517302 ° -121.543067 °	38.517080 ° -121.544264 °		63
44	6.56	6.63	Earthen Levee	Encroachments	LS	PO	Landscaping	38.516672 ° -121.546500 °	38.516427 ° -121.547595 °	Y	28
45	6.58	6.58	Earthen Levee	Trim / Thin Trees	WS	M	Thin trees to allow visibility of the ground and room to flood fight.	38.516591 ° -121.546835 °	38.516591 ° -121.546835 °		75
46	6.66	6.68	Earthen Levee	Trim / Thin Trees	LS	M	Thin trees to allow visibility of the ground and room to flood fight.	38.516261 ° -121.548153 °	38.516153 ° -121.548490 °		64
47	6.70	6.70	Earthen Levee	Trim / Thin Trees	WS	M	Thin trees to allow visibility of the ground and room to flood fight.	38.515992 ° -121.548870 °	38.515992 ° -121.548870 °		74
48	6.74	6.74	Earthen Levee	Trim / Thin Trees	LS	M	Thin trees to allow visibility of the ground and room to flood fight.	38.515841 ° -121.549507 °	38.515841 ° -121.549507 °		65
49	6.77	6.82	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.515674 ° -121.550020 °	38.515355 ° -121.550996 °		66
50	6.84	6.94	Earthen Levee	Trim / Thin Trees	WS	U	Trim trees to at least five feet above ground level.	38.515260 ° -121.551280 °	38.514587 ° -121.552922 °		29
51	6.86	6.94	Earthen Levee	Trim / Thin Trees	WS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.515077 ° -121.551659 °	38.514549 ° -121.552944 °		67
52	6.94	7.49	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.514566 ° -121.552931 °	38.507601 ° -121.557533 °	Y	68
53	6.96	7.14	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.512381 ° -121.555010 °	38.512381 ° -121.555010 °		73
54	7.01	7.63	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Add appropriate gravel or road base. Grade and compact.	38.513947 ° -121.553947 °	38.505862 ° -121.558650 °		32
55	7.01	7.83	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Keep the crown roadway free of vegetation.	38.513947 ° -121.553948 °	38.503173 ° -121.559898 °	Y	33
56	7.16	7.16	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.511994 ° -121.555212 °	38.511994 ° -121.555212 °		31
57	7.16	7.72	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.504650 ° -121.559366 °	38.504650 ° -121.559366 °		70

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

Reclamation District No. 0900

Waterway							Bank	Unit Miles	Inspection Date	Inspector	
Unit No. 01 Sacramento River							Right	7.90	09/24/2008	David Pesavento	
LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
58	7.17	7.17	Earthen Levee	Encroachments	LS	M	Prunings	38.511917 ° -121.555245 °	38.511917 ° -121.555245 °		72
59	7.19	7.20	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.511589 ° -121.555408 °	38.511443 ° -121.555483 °		34
60	7.20	7.20	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.511509 ° -121.555445 °	38.511509 ° -121.555445 °		35
61	7.23	7.23	Earthen Levee	Vegetation	LS	U	Elderberries are blocking visibility and flood fight capability.	38.511130 ° -121.555653 °	38.511130 ° -121.555653 °		36
62	7.26	7.26	Earthen Levee	Vegetation	LS	M	Elderberries are blocking visibility and flood fight capability.	38.510683 ° -121.555912 °	38.510683 ° -121.555912 °		37
63	7.28	7.28	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.510428 ° -121.556047 °	38.510428 ° -121.556047 °		38
64	7.30	7.32	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.510200 ° -121.556178 °	38.509947 ° -121.556305 °		39
65	7.32	7.32	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.509927 ° -121.556317 °	38.509927 ° -121.556317 °		40
66	7.49	7.82	Earthen Levee	Vegetation	WS	U	Remove the wild growth other than native grasses from the levee slopes.	38.507632 ° -121.557558 °	38.503201 ° -121.559882 °	Y	41
67	7.62	7.62	Earthen Levee	Trim / Thin Trees	WS	M	Thin trees to allow visibility of the ground and room to flood fight.	38.505985 ° -121.558512 °	38.505985 ° -121.558512 °		69
68	7.63	7.83	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Regrade the crown roadway for proper drainage.	38.505858 ° -121.558645 °	38.503173 ° -121.559898 °		42
69	7.75	7.77	Earthen Levee	Trim / Thin Trees	LS	U	Trim trees to at least five feet above ground level.	38.504213 ° -121.559498 °	38.503910 ° -121.559618 °		43

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

Reclamation District No. 0900

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 Sacramento River	Right	7.90	09/24/2008	David Pesavento

Levee Mile Report Line	1
Start Levee Mile	1.93
End Levee Mile	2.27
Location	
Category	Earthen Levee
Item	Vegetation
Remove/mow wild growth on landside slope within 10' of toe from LM 1.93 to LM 2.27	



Levee Mile Report Line	12
Start Levee Mile	2.56
End Levee Mile	2.64
Location	
Category	Earthen Levee
Item	Trim / Thin Trees
Trim trees to 5' from surface of levee on landside slope from LM 2.56 to LM 2.64	



Levee Mile Report Line	25
Start Levee Mile	4.25
End Levee Mile	4.25
Location	
Category	Earthen Levee
Item	Vegetation
Remove wild growth within 20' from shoulder at LM 4.25	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

Reclamation District No. 0900

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 Sacramento River	Right	7.90	09/24/2008	David Pesavento

Levee Mile Report Line	26
Start Levee Mile	4.26
End Levee Mile	4.53
Location	
Category	Earthen Levee
Item	Vegetation
Remove/mow wild growth on landside slope within 10' from toe from LM 4.26 to LM 4.53	



Levee Mile Report Line	41
Start Levee Mile	6.25
End Levee Mile	6.28
Location	
Category	Earthen Levee
Item	Trim / Thin Trees
Trim trees to 5 feet from levee surface LM 6.25-6.28	



Levee Mile Report Line	42
Start Levee Mile	6.27
End Levee Mile	6.27
Location	
Category	Earthen Levee
Item	Encroachments
Remove prunings on land shoulder at LM 6.27	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

Reclamation District No. 0900

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 Sacramento River	Right	7.90	09/24/2008	David Pesavento

Levee Mile Report Line	44
Start Levee Mile	6.56
End Levee Mile	6.63
Location	
Category	Earthen Levee
Item	Encroachments
Landscape encroachment at LM 6.56 to LM 6.63	



Levee Mile Report Line	52
Start Levee Mile	6.94
End Levee Mile	7.49
Location	
Category	Earthen Levee
Item	Vegetation
Remove wild growth 20' from waterside shoulder from LM 6.94 to LM 7.49	



Levee Mile Report Line	55
Start Levee Mile	7.01
End Levee Mile	7.83
Location	
Category	Earthen Levee
Item	Crown Surface / Depressions / Rutting
Crown of levee covered with vegetation from LM 7.00 to 7.83	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

Reclamation District No. 0900

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 Sacramento River	Right	7.90	09/24/2008	David Pesavento

Levee Mile Report Line	66
Start Levee Mile	7.49
End Levee Mile	7.82
Location	
Category	Earthen Levee
Item	Vegetation
Remove/mow wild growth 20' from waterside shoulder at LM 7.49 to LM 7.82	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2008 Levee Inspection Results

Reclamation District No. 0900

Waterway			Bank	Unit Miles
Unit No. 02 Yolo Bypass			Left	5.70
	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	3/24/2008		9/24/2008	
DWR Inspector	Richard Willoughby		David Pesavento	
Accompanied By				
Unit Maintenance Rating (Fall Only)			U	

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

Reclamation District No. 0900

Waterway						Bank	Unit Miles	Inspection Date		Inspector	
Unit No. 02 Yolo Bypass						Left	5.70	09/24/2008		David Pesavento	
LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.05	0.05	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.581448 ° -121.567752 °	38.581448 ° -121.567752 °		6
2	0.95	0.95	Earthen Levee	Cracking	WS	M	Monitor and have inspected by geotechnical engineer. Inspector Comments: Cracks located on waterside on ramp toward under I-80, some slumping	38.574250 ° -121.581517 °	38.574250 ° -121.581517 °	Y	10
3	3.07	3.28	Earthen Levee	Vegetation	LS	U	Remove the wild growth other than native grasses from the levee slopes.	38.543752 ° -121.582217 °	38.517068 ° -121.582191 °	Y	14
4	3.08	3.26	Earthen Levee	Crown Surface / Depressions / Rutting	CR	U	Regrade the crown roadway for proper drainage.	38.543474 ° -121.582246 °	38.540944 ° -121.582213 °	Y	15
5	3.43	3.43	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.538513 ° -121.582167 °	38.538513 ° -121.582167 °	Y	19
6	4.02	4.29	Earthen Levee	Animal Control	WS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.529920 ° -121.582100 °	38.525985 ° -121.582098 °	Y	3
7	4.91	4.91	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.517129 ° -121.582129 °	38.517129 ° -121.582129 °		20
8	4.98	4.98	Earthen Levee	Cracking	LS	M	Monitor and have inspected by geotechnical engineer. Inspector Comments: Cracks noted at both waterward and landward shoulders of levees.	38.516096 ° -121.582201 °	38.516096 ° -121.582201 °	Y	17

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

Reclamation District No. 0900

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 02 Yolo Bypass	Left	5.70	09/24/2008	David Pesavento

Levee Mile Report Line	2
Start Levee Mile	0.95
End Levee Mile	0.95
Location	
Category	Earthen Levee
Item	Cracking
Crack located on ramp on waterside of levee at LM 0.95.	



Levee Mile Report Line	2
Start Levee Mile	0.95
End Levee Mile	0.95
Location	
Category	Earthen Levee
Item	Cracking
Closer view of crack at LM 0.95.	



Levee Mile Report Line	3
Start Levee Mile	3.07
End Levee Mile	3.28
Location	
Category	Earthen Levee
Item	Vegetation
Remove/trim brush on landside of levee to 10 feet from the toe from LM 3.07 to LM 4.91.	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

Reclamation District No. 0900

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 02 Yolo Bypass	Left	5.70	09/24/2008	David Pesavento

Levee Mile Report Line	4
Start Levee Mile	3.08
End Levee Mile	3.26
Location	
Category	Earthen Levee
Item	Crown Surface / Depressions / Rutting
Multiple, large, deep depressions located in levee crown from LM 3.08 to LM 3.26.	



Levee Mile Report Line	5
Start Levee Mile	3.43
End Levee Mile	3.43
Location	
Category	Earthen Levee
Item	Animal Control
Repair damage to levee from rodents at LM 3.43	



Levee Mile Report Line	6
Start Levee Mile	4.02
End Levee Mile	4.29
Location	
Category	Earthen Levee
Item	Animal Control
Example of rodent burrow on waterside of levee from LM 4.02 to LM 4.29.	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

Reclamation District No. 0900

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 02 Yolo Bypass	Left	5.70	09/24/2008	David Pesavento

Levee Mile Report Line	8
Start Levee Mile	4.98
End Levee Mile	4.98
Location	
Category	Earthen Levee
Item	Cracking
Crack located on landward shoulder around LM 4.98.	



Levee Mile Report Line	8
Start Levee Mile	4.98
End Levee Mile	4.98
Location	
Category	Earthen Levee
Item	Cracking
Crack located on waterward shoulder around LM 4.98.	



Levee Mile Report Line	8
Start Levee Mile	4.98
End Levee Mile	4.98
Location	
Category	Earthen Levee
Item	Cracking
Closer view of landward crack around LM 4.98; please note black pen for scale.	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected